# Industrie

## 281 • 285 • MH

### Spring and Hanging Scales



**Hand strap** 

KERN MH

Order Hotline:

STANDARD

0.00

Go to back page of catalogue



#### Standard



TAR Tare: put back displayed value to "0" during weighing process, e.g. to add or remove weighing material from a container.







Accuracy of ± 0,3% of the load. The taring range is 20% from Max. A conversion of the pressure measurement is possible from a Max 300 g (option)

| Model   | Read-<br>out<br>d | Weighing range Max | Load-<br>bearing<br>with |     |  |
|---------|-------------------|--------------------|--------------------------|-----|--|
|         | g                 | g                  | 10.15-2                  | mm  |  |
| 281-101 | 0,1               | 10                 | ≪0                       | 80  |  |
| 281-151 | 0,25              | 30                 | ≪€                       | 80  |  |
| 281-201 | 0,5               | 60                 | ≪0                       | 80  |  |
| 281-301 | 1,0               | 100                | ≪0                       | 80  |  |
| 281-401 | <b>5</b> 2,0      | 300                | ≪0                       | 100 |  |
| 281-451 | 5,0               | 600                | ≪e                       | 100 |  |
| 281-601 | 10,0              | 1000               | ≪e                       | 100 |  |
| 281-752 | <b>6</b> 20,0     | 2500               | Con                      | 100 |  |

| Model   |   | Read-<br>out<br>d | Weighing<br>range<br>Max<br>kg | Load-<br>bearing<br>with | Unit<br>length<br>mm |  |
|---------|---|-------------------|--------------------------------|--------------------------|----------------------|--|
| 285-052 | 6 | 50                | 5                              | Con                      | 140                  |  |
| 285-102 | 6 | 100               | 10                             | Co                       | 140                  |  |
| 285-202 | 6 | 200               | 20                             | C-0                      | 140                  |  |
| 285-352 | 6 | 500               | 35                             | Ca                       | 90                   |  |
| 285-502 | 6 | 500               | 50                             | Ca                       | 90                   |  |



Models KERN 285 are equipped with a drag pointer 1 and handle (2)



Pressure set for models [] KERN 281-890 and models [6] KERN 285-890 available at an additional price

Special models, e.g. in Newton, as well as accessories, are described in detail in the KERN brochure "spring balances". Please request free of charge



#### Ready for use

Battery size AA (2x 1,5 V) included. AUTO-OFF function after 5 min without a change of load to preserve the battery. Operating time approx. 250 h

#### 3-pack order example: KERN MH 5K5 -S3 6-pack order example: KERN MH 5K5 -S6

| Model<br>KERN | Read-<br>out<br>d | Weighing<br>range<br>Max<br>kg | 1 piece | 3-Pack | 6-Pack |
|---------------|-------------------|--------------------------------|---------|--------|--------|
| MH 5K5        | 5                 | 5                              |         |        |        |
| MH 10K10      | 10                | 10                             |         |        |        |

Case WxDxH 70x25x100 mm (with hook 140 mm). Net weight approx. 150 g. LCD display, digit height 12 mm.

Your KERN specialist dealer

#### KERN - Your DKD-Calibration Partner



